



# PRICE LIST FOR REPAIRS WITH COSTS

VALID FROM 01/10/2018 - PRICES INCLUDE VAT

REPAIR TYPE	PRICE
<b>Buckle</b>	13,53 €
<b>Padding on the back</b>	18,45 €
<b>Hole (colour differences may arise) *</b>	18,45 €
<b>Velcro (black if colour not available)</b>	13,53 €
<b>Replacement of a soft handle (webbing)</b>	14,15 €
<b>Replacement of a reinforced handle</b>	18,45 €
<b>Replacement shoulder strap</b>	15,99 €
<b>Belt</b>	6,15 €
<b>Lock / TSA Lock</b>	18,45 €
<b>Seams</b>	13,53 €
<b>Telescopic handle</b>	24,60 €
<b>1 Wheel</b>	15,99 €
<b>2 Wheels</b>	24,60 €
<b>Zipper rucksacks and schoulde bags</b>	19,68 €
<b>Zipper small bags (smaller than Padded Pak'r)</b>	15,99 €
<b>Zipper duffels (no wheels)</b>	24,60 €
<b>Zipper trolleys</b>	30,75 €
<b>Zippers for wallets, (school) accessories</b>	14,76 €
<b>Additional zippers (small pockets)</b>	14,76 €

\* The total cost of repair is estimated after evaluation of the product. We will do our utmost to repair non-warranty products to their original form as well as possible. Sometimes it is only possible to add extra seams or to use materials with a slight colour difference compared to the original colour of the product. In many cases we can only repair with a contrasting colour such as black or grey. We do not replace complete panels. The total cost of repair is finally estimated once we finish evaluation on-site at the repair center.